KLUŚ | Inspiring Solutions
®

Parts needed to mount the ST standard head

Head (B)

Mounting bracket (A)

Tools needed for mounting:

- Allen wrench

**NOTE!** A list of products corresponding with the selected accessories is available at www.KlusDesign.eu

1. Insert the lighting fixture into the mounting bracket (A).

A

2. Mount the arm in the head (B) by tightening the pressure screw in the head with the Allen wrench.

B

3. NOTE! The position of the lighting fixture on the arm can be adjusted in the range of 360° (depending on the distance of the fastener from the edge of the extrusion).

360°