KLUŚ **Inspiring Solutions** ®

Parts needed to mount the JAZ extrusion

Extrusion (A)

LED strip (B)

Hanger (C)

Cover (D)

End cap (E)

Tools needed for mounting:

- drill

NOTE! All LED strips must be connected to a 12 V or 24 V power supply.

IMPORTANT: The manual presents the simplest mounting procedure.
More mounting procedures and related accessories can be found at klusdesign.eu

**1.** Drill a hole in the extrusion (A) to feed the power cable.

cross-section

A

top view

2. Mount the LED strip (B) in the extrusion.

B

3. Suspend the extrusion using the hangers (C) and a chosen suspension system. The hanger manual can be downloaded at klusdesign.eu/uk.

cross-section

C

top view

5. Connect power to the LED strips. Insert the cover (D) and the end caps (E).

E

D