

Parts needed to mount the PAC-ALU extrusion



Extrusion (A)



End caps (B)



Cover (C)



LED strip (D)


Tools needed for mounting:

- mounting glue

WARNING! All LED strips should be connected to a 12 V or 24 V power supply.

IMPORTANT: The mounting instructions present the basic form of assembly. More methods and related accessories can be found at www.KlusDesign.eu

1. Mount the LED strip (D), insert the cover (C), and then insert the end cap (B). Feed the power cable.



2. Apply glue to the mounting surface. Connect power and mount the extrusion.

