


1. K-10 Mounting bracket (ref. 24340)
2. Screw
3. Lighting fixture
4. Power supply (12 V / 24 V)

\*The full range of accessories and electronics is available at [www.KlusDesign.eu](http://www.KlusDesign.eu)

**NOTE!** All LED tapes must be connected to a 12 V or 24 V power supply.

**IMPORTANT:** Not all possible mounting procedures are presented here. More mounting procedures and related accessories can be found at [www.KlusDesign.eu](http://www.KlusDesign.eu). Drawings of extrusions and accessories in these instructions are simplified and only approximate the actual shapes.




Screw the K-10 mounting brackets (1) to the surface with the use of screws (2). the brackets must be aligned in a straight line.

It is recommended to use:

- 2 mounting brackets for 1 m of fixture
- 4 mounting brackets for 2 m of fixture
- 5 mounting brackets for 3 m of fixture

**NOTE!** It is necessary to use countersunk screws dedicated to the particular type of surface. Diameter of the screws cannot exceed 3 mm / 0.12".



Connect the fixture (3) to the power supply (4) and mount it in the brackets.