


1. Attach the mounting bracket to the surface with screws.

2. Insert the extrusion into the mounting bracket.



NOTE! A list of products corresponding with the selected accessories is available at www.KlusDesign.eu